



Tubing Gauge No. and Decimal Chart

Gage No.	Gage Decimal	Gage No.	Gage Decimal
0	0.34	15	0.072
1	0.3	16=1/16"	0.065
2	0.284	17	0.058
3	0.259	18	0.049
4=1/4"	0.238	19	0.042
5	0.22	20	0.035
6	0.203	21	0.032
7=3/16"	0.18	22	0.028
8	0.165	23	0.025
9	0.148	24	0.022
10	0.134	25	0.02
11=1/8"	0.12	26	0.018
12	0.109	27	0.016
13	0.095	28	0.014
14	0.083	29	0.013